



Project site after 2/15-2/17 rain event: basin upstream (above) and basin outlet downstream (below)





Stabilized site of former rental house (above) and sewer manholes in basin with added concrete collars to prevent floatation (below)

